

1. Insert bulb(A) into socket one by one
2. Hang the CRS22380-Q, CRS22380-S, CRS22380-R to the metal ring(B) by mix
3. Hang the CRS22380-P, CRS22380-M, CRS22380-N to the metal ring(C) by mix
4. Hang the CRS22380-L, CRS22380-K to the metal ring(D) to the metal ring(D) by mix

